Message Text

LIMITED OFFICIAL USE

PAGE 01 NIAMEY 01920 221550Z

44

ACTION OC-05

INFO OCT-01 AF-06 ISO-00 CCO-00 OCE-00 /012 W

----- 016756

O 221524Z MAY 75 ZFF-6 FM AMEMBASSY NIAMEY TO SECSTATE WASHDC IMMEDIATE 0720 AMEMBASSY ACCRA IMMEDIATE INFO AMEMBASSY NDJAMENA IMMEDIATE

LIMITED OFFICIAL USE NIAMEY 1920

ACCRA FOR RCO; NDJAMENA FOR CEO

E.O. 11652 N/A TAGS: ABM

SUBJECT: WATTS LP ANTENNA FAILURE

REF* A. STATE 118899; B. NIAMEY 1900

- 1. ANTENNA TIED TO TREES AND HOLDING STEADY. COAX LEAD IS OKAY.
- 2. RE PARA 3 REF B: ON JONES TYPE PLUG P406CCT PINS 8, 9, UV 1P AND 12 ARE ALL SHORTED TOGETHER.
- 3.32SCALED ANTENNA AGAIN, THIS TIME WITH VOM, TO CHECK FOR SHORTS IN ROTATOR. ALL RPT ALL MOTOR LEADS ARE SHORTED TOGEHTER.
- 4. BELIEVE BEST POSSIBLE SOLUTION TO PROBLEM IS REPLACE ENTIRE RTOATOR. IF NIAMEY ROTATOR STILL UNDER WARRANTY, RETURN DEFECTIVE UNIT TO HY-GAIN AND INSTALL NEW ONE. IF WARRANTY EXPIRED, INSTALL NEW ONE AND SALVAGE ANY PARTS STILL USABLE FROM OLD ROTATOR AND USE THEM FOR SPARES.
- 5. ALSO RECOMMEND NEW DONTROL CABLE. WILL AR 500 FEET. WILL ALSO NEED ONE JONES TYPE PLUG P406CCT AND ONE PLUG TYPE MS-3106A-18-12S. LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 NIAMEY 01920 221550Z

- 6. PRESENTLY WORKING NOUAKCHOTT AT 150 WATTS USING LP.
- 7. FVLAN TO CONDUCT TESTS WITH NDJAMENA ON SYSTEM TWO USING WHIP.
- 8. NEW BUT RELATED SUBJECT: USED TODAY'S OPPORTUNITY AT TOP OF ANTENNA TO CHECK AIRCRAFT NUTS; THEY ARE HOLDING FIRM. BELPUVE THAT PARTICULAR PROBLEM HAS BEEN NLVED.
- 9. FYI: THIS CRO IS BEGINNING TO FEEL LIKE AN EAGLE.BUCHE

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 22 MAY 1975 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: RELEASED Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: buchant0
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1975NIAMEY01920

Document Number: 1975NIAMEY01920 Document Source: CORE Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D750180-0051

From: NIAMEY

Handling Restrictions: n/a

Image Path:

Legacy Key: link1975/newtext/t19750527/aaaaayfx.tel Line Count: 71 Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION OC

Original Classification: LIMITED OFFICIAL USE

Original Handling Restrictions: n/a
Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE Previous Classification: LIMITED OFFICIAL USE Previous Handling Restrictions: n/a Reference: 75 * STATE 118899, 75 NIAMEY 1900 Review Action: RELEASED, APPROVED Review Authority: buchant0

Review Comment: n/a Review Content Flags: Review Date: 26 AUG 2003

Review Event:

Review Exemptions: n/a
Review History: RELEASED <26 AUG 2003 by BoyleJA>; APPROVED <10 DEC 2003 by buchant0>

Review Markings:

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JÚL 2006

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: WATTS LP ANTENNA FAILURE TAGS: ETEL, OGEN To: STATE ACCRA

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JUL 2006